
Trendline
Percent Solids, Measure Values
fail paint filter
pass paint filter
pass paint filter, 12, 59
Percent Solids
Days
100
90
80
70
60
50
40
30
20
10
0
0
5
10
15
20
25
30